
TECHNICAL BULLETIN

Solubility of boric acid and sodium borates



Percentage by weight of solution, in terms of fully hydrated salts.

Note: Formulae listed represent the solid phases present at the corresponding temperatures and are not used in calculations.



Temperature °C

*Kernite may be formed upon slowly lowering of the temperature of a saturated solution.



1 of 1 (4/2025)